







2018 User Symposium

1F-5 PPC Refresh









1F-5 PPC System Refresh

- GE Designed BWR-4 (same as 1F-2, 1F-3 and 1F-4)
- Replacement of Original system by TEPSCO and Scientech started in Oct 2009
- In final stages of commissioning the replacement system at the time of the earthquake and tsunami at Fukushima Daiichi
 - Hardware fully installed
 - Software mostly installed



1F-5 PPC System Functions (Before Accident)

- R*TIME Functions of 1F-5 PPC (Usual BWR PPC function)
 - Redundant System
 - RTP I/O Interface (apx AI :2000 DI:1000)
 - Calculations / Alarming / Archive...
 - Other External system Interface
 - BOP Calculation
 - Site Specific Displays



3.11 Accident (Earthquake and Tsunami)

- 1F-5 unit not operating, in final stages of completing a refueling and maintenance outage.
- Replacement 1F-5 PPC fully installed and in final stages of testing.
- Units 1F-5 and 1F-6 experienced minimal damage from the Tsunami
 - Safety related system worked well for shutting down
 - Units maintained emergency backup power from one diesel generator
 - Units are located at a higher elevation relative to sea level than units 1F-1 through 1F-4



1F-5 PPC System Functions (Post Accident)

R*TIME Functions of 1F-5 PPC

After the accident, unit 5 remained shut down so many of points and functions were not used

- Basic R*Time system (Redundant / Calculation / Alarming...)
- Many of RTP I/O Points without monitoring (75% points unused)
- Also many external Interfaces not used



1F-5 PPC System Functions (Post Accident)

- R*TIME Functions of 1F-5 PPC not used
 - Engineering Server Interface (PSS)
 - RWM
 - TRA Interface
 - CMS Interface
 - External Transmission System Interface
 - Modbus Interface (Megawatt Meter)
 - BOP (Calculation, Log, Display and Report)
 - Site Specific Displays for operating



1F-5 PPC Refresh

- Reduced function PPC system required for data monitoring through decommissioning
- Project Initiated in DEC/2017 to refresh 1F-5 PPC System
- Minimum Cost and Period were required





1F-5 PPC Refresh (Upgraded Components)

- Upgraded Hardware / Software
 - PPC Servers Hardware (DC Servers)
 FUJITSU PRIMERGY RX2540 M4
 - PPC Server Software (Virtual Environment)

VMWare ESXI



1F-5 PPC Refresh (Maintained Components)

Software Upgraded

R*Time software was not upgraded basically


- Upgraded software were below
- System monitoring (for New Server)
- Interpretive Calculations (Eliminated MKS Toolkit ,LEX and YACC)

License was tied to original PPC server hardware and could not be transferred to replacement hardware



1F-5 PPC Refresh (Refresh Image)

- H/W Refresh Image
 - Prepare New Phisical Servers
 - P2V R*TIME Server, Create New AD Server





Project Duration 4 months

- Start 12 / 2017 Complete 03 / 2018

	2017	2018		
	DEC	JAN	FEB	MAR
H/W Design Setting-Up(Fujitsu)				
VM Ware Config (Software house)				
R*Time Config (TEPSCO)				
FAT (TEPSCO / Sientech)				
SAT (TEPSCO)				



1F-5 PPC Refresh Issues

- VM Configuration did not support most system monitoring data (SNMP) for the server computers so monitor alternative way
 - Fans
 - Power Supplies
 - Other OEM specific data
- Calculation
 - MKS Toolkit, LEX and YACC did not run at Virtual Environment so select alternative executable

Original SW licenses tied to PPC server hardware and could not be transferred.



1F-5 PPC Refresh Issues

- RTP 2300 I/O Equipment Verification
 - TEPCO / TEPSCO does not have RTP 2300 I/O equipment in development system
 - VM images created and sent to Scientech for testing using Scientech equipment
 - Significant difficulty in creating and transferring VM images to Scientech but testing was well done



PPC Replacement Issues (common 1F-5 and 6)

Entire 1F Site Considered an RCA

- RWP and dosimetry required to work in 1F-5 and 6 computer room and control room
- Limitation on number of work hours per day

Resources

 Concurrent with 1F-5/6 PPC projects so assigned engineers more efficiently

