

Sask Power ER Successes


August 2010





Prologue

- The Beginning
- The Deployment
- The Finds
- The Example Catches
- The Q&A



SaskPower has granted Scientech permission to use the information in this report as part of Scientech's presentation at the "2010 Users Symposium: Fleet Management and Optimization Solutions, August 17-20, 2010". SaskPower makes no representation of any kind regarding the accuracy or quality of the information presented and any use or further distribution of any of the information in this report is done so at the user's sole risk.



The Beginning

- God created North America
- Pioneers founded Canada
- Soon after Sask Power became a reality
- Two men with deep fore-thinking abilities emerged
- Began a quest to find a key supplier who could help improve - unit availability, equipment reliability, cycle efficiency
- Scientech was discovered and FAMOS was acquired
- Happiness and benefits now reign in the province





The Deployment

PMAX, PdP and Rules Engine deployed at:

- Popular River 1 October 2008 (32 models)
- Popular River 2 June 2008 (32 models)
- Shands 1 August 2009 (49 models)
- Boundary Dam 3,4,5,6, December 2009 (126 models)
 Totals: 7 Units, 239 component models

Pending deployments:

- Boundary Dam 1,2 ~December 2010 (60 models)
- Queen Elizabeth 1,2,3,4,5,6,7,8,9, ~January 2011 (44+ models)
- Cypress & Centennial Wind Farms 2011 (99+ models)
- _ ?



The Deployment -cont.

- Applications deployed on central corporate servers
- Sask central support engineering personnel primary users
- Site cognizant person being established per site
- Engaging Scientech for remote Monitoring & Diagnostic (M&D) support





The Finds

Over 22 months of involvement, PdP identified:

- >120 anomalous equipment situations
- Several equipment condition anomalies
- variety of signal/sensor issues






The Example Catches

- 1. U1 Deaerators
 - steam extraction valve problem: \$44K avoided costs
 - flow orifice installed improperly: >\$100K avoided costs
- 2. #2A & #2B Primary Air Fan High winding temps due to motor air filter plugging problems
 - \$30K \$600K avoided costs
- **3. #2B Boiler Feed Pump** Aux Lube Oil Pump continuously running
 - \$15K \$30K avoided costs
- 4. #1B Primary Air Fan Bearing vibration problem
 - >\$100K possible



The PR1 Deaerator Story

- After unit returned to service, the Deaerator was not performing as before
- Extraction steam temp & pressure dropped considerably
- No Operator concern identified
- Found steam trap on extraction valve not fully opened
- Ultimately found extraction steam trap was plugged









The SH1 Deaerator Story -2

- After start-up, problems with condenser backpressure
- Performed testing, closed extraction steam valve
- Never re-energized control drive for valve
- No indication of problem on Operator DCS screens
- No serious problem, but could have affected heat rate








The #2A & #2B Primary Air Fan Motor Story

- After model retraining, identified increasing winding temps
- Indications were of a motor cooling problem
- Found plugged filters
- No indication of problem on Operator DCS screens
- Could have led to cycle inefficiencies, higher load draw, or motor failure









The #2B Primary Air Fan Motor Story

- PdP identified cyclic winding temp conditions (correlated with plugged air filters)
- 2A was responding different
- Inspection of 2B found wrong size (finer) filter
- Could have led to cycle inefficiencies, higher load draw, or motor failure








The #2B BFP Oil Pump Story

- PdP identified lube oil pressure change, much higher than should be
- Found Aux Oil Pump was continually running in "Auto" (normally "off")
- No DCS alert to Operators
- If left on continuously, could have led to Aux Oil Pump failure, or BFP bearing problems









The #1B Primary Air Fan Story

- PdP identified very early indication of a InBd Bearing vibration concern
- The PdP identified step change of OtBd Bearing vibration
- Then PdP re-alerted on the InBd Bearing
- Vibration study did not identify anything significant
- 4 days later, fan bearing failed
- Potential avoided costs >\$100K








Also, #6 Condensate Extraction Pump Story

- PdP identified decreasing
 Feedwater Htr low control valve position at full load
- Reviewed drain line configurations
- Determined probable problem with alternate drain line
- Drain inspected and adjustments made to the heater drain valve configuration, no further control valve problem





The Q & A



Continued success is the result of continued improvement.